

Reactive Blue 5RH
C.I. Reactive Blue 13

Light	:	6
Washing	:	4
Washing (Stain)	:	4-5
Perspiration	:	4-5
Substantivity	:	Low
Dischargeability	:	Poor
Hypochlorite	:	3-4
Solubility at 60°C	:	100 g/l

1% Cotton Dyeing
4% Cotton Dyeing
1% Cotton Printing
4% Cotton Printing



Reactive Black HN
C.I. Reactive Black 8

Light	:	6
Washing	:	5
Washing (Stain)	:	5
Perspiration	:	4-5
Substantivity	:	Low
Dischargeability	:	Poor
Hypochlorite	:	4
Solubility at 60°C	:	40 g/l

1% Cotton Dyeing
4% Cotton Dyeing
1% Cotton Printing
4% Cotton Printing

