

Reactive Blue 3R
C.I. Reactive Blue 28

Light	:	6-7
Washing	Effect	: 3-4
	Stain	: 5
Perspiration Acidic	:	4R
Bleaching Hypochlorite	:	4-5
Chlorinated Water	:	3-4
Dischargeability	:	Moderate
Solubility at 60°C	:	80 g/l

1% Cotton Dyeing
4% Cotton Dyeing
4% Cotton Printing
2% Discharge Printing



Reactive Dark Blue HR
C.I. Reactive Blue 89

Light	:	6
Washing	Effect	: 4
	Stain	: 3
Perspiration Acidic	:	5
Bleaching Hypochlorite	:	1
Chlorinated Water	:	2-3 R
Dischargeability	:	Moderate
Solubility at 60°C	:	100 g/l

1% Cotton Dyeing
4% Cotton Dyeing
4% Cotton Printing
2% Discharge Printing

